

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

JL1324  
NNE  
> 1  
1.690 mi.  
8924 ft.

MANHOLE #1429  
CONEY ISLAND AVE/AVE T  
BROOKLYN, NY

NY Spills S106470837  
N/A

Site 2 of 3 in cluster JL

Relative:  
Higher

Actual:  
19 ft.

SPILLS:

Name: MANHOLE #1429  
Address: CONEY ISLAND AVE/AVE T  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0403772 / 2005-07-26  
Facility ID: 0403772  
Facility Type: ER  
DER Facility ID: 197376  
Site ID: 239944  
DEC Region: 2  
Spill Cause: Unknown  
Spill Class: C4  
SWIS: 2401  
Spill Date: 2004-07-08  
Investigator: JHOCONNE  
Referred To: Not reported  
Reported to Dept: 2004-07-08  
CID: 404  
Water Affected: Not reported  
Spill Source: Commercial/Industrial  
Spill Notifier: Affected Persons  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False

Remediation Phase: 0  
Date Entered In Computer: 2004-07-08  
Spill Record Last Update: 2005-07-26  
Spiller Name: Not reported  
Spiller Company: CON ED  
Spiller Address: Not reported  
Spiller Company: 999  
Contact Name: ERT DESK  
DEC Memo:

"Prior to Sept, 2004 data translation this spill Lead\_DEC Field was  
O'CONNELL e2mis no. 154254: FDNY REPORTED THAT MH1429 LOCATED N/W/C/  
CONEY ISLAND AVE & AVE T WAS ON FIRE W/SMOKE. EDWARDS REPORTS FINDING  
BLOWN JOINT IN THE STRUCTURE, WITH APPX 4 GALLONS OF OIL, NO WATER,  
IN SAID STRUCTURE. Cannot clean structure until FOD tags structure.  
FOD General reports waiting for TC on fdr. Will advise when TC is on.  
Clean up pending deenergization of FDR and FOD. UPDATE 09-JUL-2004  
06:12 HRS. ENVIR. OPER. O.S. E.WILLIAMS EMP# 56346 REPORTS: CREW  
FOUND A PLUGGED DRAIN IN STRUCTURE AND SEALED SAME WITH CEMENT.  
Update 7/9/04 9:00 hrs. O.S. B. Bamonte reports on location with  
Glodowski, Colanero, & Fernandez. Clean up was treated 50-499.  
Structure was double washed with bio-gen 760. No sump was found in  
structure. An Env. stop tag # 39288 was hung. Tag will remain in  
place pending sample results. 7/09/2004 09:24 HRS. -- RECEIVED PCB  
RESULTS: LAB SEQ # 04-05362, 5 PPM, AROCLOR 1254. 7/09/2004 23:45  
HRS. -- NOTIFIED BROOKLYN ENV OPS O/S E. WILLIAMS THAT SINCE CLEANUP  
IS COMPLETE AND PCB RESULTS CAME BACK 5 PPM, IT APPEARS THE ENV. STOP  
TAG CAN BE PULLED AND THE INCIDENT CLOSED OUT. 7/10/2004 02:45 HRS.  
-- J. MIDDLETON OF BROOKLYN ENV OPS REPORTS THAT HE OPENED MANHOLE  
AND DID NOT FIND AN ENV. STOP TAG. IN STRUCTURE. HE SPOKE WITH ENV

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Remarks:

OPS O/S E. WILLIAMS WHO SAID THAT TAG WAS PROBABLY REMOVED BY UNDERGROUND. INCIDENT HAS BEEN CLOSED OUT AS OF THIS TIME 11/04/04 08:45 UPDATE: REPAIRS TO BLOWN JOINT WERE COMPLETED BY UNDERGROUND ON 7/09/04 . INCIDENT IS CLOSED."  
"NO WATER IN STRUCTURE. FIRE DEPT ON SCENE. UNKNOWN IF ANY SEWER OF SUMPS IN STRUCTURE AT THIS TIME. CON ED REF \$154254."

All Materials:

Site ID: 239944  
Operable Unit ID: 886186  
Operable Unit: 01  
Material ID: 491332  
Material Code: 0066A  
Material Name: unknown petroleum  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: 2.00  
Units: G  
Recovered: .00  
Oxygenate: Not reported